


3200-4566 Kytentäöhje  
3200-4566 Wiring instructions



- 1 Kierroslukumittari (W)
- 2 B(+) Akku
- 3 Merkkivalo (D+)

- 1 Tachometer (W)
- 2 B(+) Battery
- 3 Indication lamp (D+)